

Exhibit 1

12324	CN	3/27/03	Chart (attached to claim form)	List of buildings with date building and square feet	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	3/20/90	Report	Bulk Sample Analysis by Pinchin & Associates - Lab Ref # b1037	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	3/20/90	Report	Bulk Sample Analysis by Pinchin & Associates - Lab Ref # b1038	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	3/20/90	Report	Bulk Sample Analysis by Pinchin & Associates - Lab Ref # b1051	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	4/17/90	Report	Bulk Sample Analysis by Pinchin & Associates - Lab Ref # b1142	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	4/20/90	Invoice	Bulk Sample Analysis by Pinchin & Associates - Lab Ref # b1185	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	5/16/90	Invoice	Invoice from Pinchin & Associates - \$7,000.00	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	4/23/90	Report	Addendum One, Asbestos Removal, 4 and 8 Assiniboine Road, York University	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	4/17/90	Letter	Letter from Pinchin & Associates to Robert Halsall and Associates re: Asbestos Removal Project	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	4/17/90	Letter	Letter from Pinchin & Associates to York University re: Clarification re: Consulting Services	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	4/17/90	Letter	Letter from Pinchin & Associates to York University re: Consulting Services, Asbestos Removal, 4 and 8 Assiniboine Drive Apts.	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	3/28/90	Letter	Letter from Pinchin to York University re: Asbestos Texture Plaster, The Assiniboine Apts.	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	4/18/90	Letter	Letter from Pinchin to York University re: Impact of Column Recladding on Asbestos Texture Plaster, 6 Assiniboine Drive	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	4/11/90	Letter	Letter from Pinchin to York University re: Friable Asbestos Materials - 2,4,6,8 Assiniboine Road	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	Undated	Report	Specifications - Asbestos Removal - Type 3	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	5/8/90	Letter	Letter from Pinchin to York University re: Impact of Texture Plaster, Re-cladding of 6 Assiniboine	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	5/29/90	Report	Bulk Sample Analysis by Pinchin & Associates - Lab Ref. # b1297	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	6/5/90	Report	Bulk Sample Analysis by Pinchin & Associates - Lab Ref. # b1331	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	6/5/90	Report	Bulk Sample Analysis by Pinchin & Associates - Lab Ref. # b1334	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	6/8/90	Report	Bulk Sample Analysis by Pinchin & Associates - Lab Ref. # b1358	100 Oak Street Hampton, SC	Speights & Runyan

12324	CN	7/17/90	Report	Bulk Sample Analysis by Pinchin & Associates - Lab Ref. # b1502	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	9/20/90	Invoice	Invoice from Pinchin & Associates - \$45,854.89	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	1/22/91	Report	Inspection and Air Monitoring Asbestos Removal at 4 and 8 Assiniboine Road, York University	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	5/14/90	Report	Job 1948	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	6/8/90	Letter	Letter from Pinchin to York University re: Concrete Levelling Compound - 4 and 8 Assiniboine Road	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	1/30/91	Invoice	Invoice from Pinchin & Associates - \$2,040.00	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	8/15/90	Report	Inspection and Air Monitoring Asbestos Removal at 4 and 8 Assiniboine Road, York University	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	1/22/91	Report	Asbestos-Containing Concrete Levelling Compound at 4 and 8 Assiniboine Road, York University	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	4/18/94	Report	Bulk Sample Analysis by Pinchin Environmental - Lab Ref. # b6637	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	5/4/94	Report	Bulk Sample Analysis by Pinchin Environmental - Lab Ref. # b6737	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	9/21/94	Invoice	Invoice from Pinchin Environmental - \$1,968.69	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	4/13/94	Letter	Letter from Pinchin to York University re: Boiler No. 4 - Central Utility Building	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	6/7/94	Memo	Faxnote from Pinchin Environmental to York University	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	6/00/94	Report	Project Scope and Details - Central Utility Building	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	6/00/94	Report	Asbestos Removal - Type 2 Method - Central Utility Building	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	6/00/94	Report	Asbestos Removal - Type 3 Method - Central Utility Building	100 Oak Street Hampton, SC	Speights & Runyan
12324	CN	6/07/94	Report	Pinchin Summary	100 Oak Street Hampton, SC	Speights & Runyan